DocuSign Envelope ID: 7AD99AF5-95D8-4C85-B9D7-661DA5DC32DE

PROPERTY TRANSFER NOTIFICATION CERTIFICATION

This form is to be signed by the prospective purchaser before signing a purchase and sale agreement or a memorandum of agreement, or by the lessee-prospective purchaser before signing a lease with an option to purchase for residential property built before 1978, for compliance with federal and Massachusetts lead-based paint disclosure requirements.

Required Federal Lead Warning Statement:

Every purchaser of any interest in residential property on which a residential dwelling was built prior to 1978 is notified that such property may present exposure to lead from lead-based paint that may place young children at risk of developing lead poisoning. Lead poisoning in young children may produce permanent neurological damage, including learning disabilities, reduced intelligence quotient, behavioral problems and impaired memory. Lead poisoning also poses a particular risk to pregnant women. The seller of any interest in residential real property is required to provide the buyer with any information on lead-based paint hazards from risk assessments or inspections in the seller's possession and notify the buyer of any known lead-based paint hazards. A risk assessment or inspection for possible lead-based paint hazards is recommended prior to purchase.

Seller's Disclosure

(a) Presence of lead-based paint and/or lead-based paint hazards (check (i) or (ii) below):

(i) __X__ Known lead-based paint and/or lead-based paint hazards are present in the housing (explain).

http://webapps.ehs.state.ma.us/Leadsafehomes/default.aspx . Previous owner reports attached.

(ii) _____ Seller has no knowledge of lead-based paint and/or lead-based paint hazards in the housing.

(b) Records and reports available to the seller (check (i) or (ii) below):

(i) __X__ Seller has provided the purchaser with all available records and reports pertaining to lead-based paint and/or lead-based paint hazards in the housing (check documents below).

[X] Lead Inspection Report; [X] Risk Assessment Report; [ ] Letter of Interim Control; [X] Letter of Compliance

(ii) _____ Seller has no reports or records pertaining to lead-based paint and/or lead-based paint hazards in the housing.

Purchaser's or Lessee Purchaser's Acknowledgment (initial)

(c) _____ Purchaser or lessee purchaser has received copies of all documents checked above.

(d) _____ Purchaser or lessee purchaser has received no documents.

(e) _____ Purchaser or lessee purchaser has received the Property Transfer Lead Paint Notification.

(f) _____ Purchaser or lessee purchaser has (check (i) or (ii) below):

(i) _____ received a 10-day opportunity (or mutually agreed upon period) to conduct a risk assessment or inspection for the presence of lead-based paint and/or lead-based paint hazards; or

(ii) _____ waived the opportunity to conduct a risk assessment or inspection for the presence of lead-based paint and/or lead-based paint hazards.

Agent's Acknowledgment (initial)

(g) __MB__ Agent has informed the seller of the seller's obligations under federal and state law for lead-based paint disclosure and notification, and is aware of his/her responsibility to ensure compliance.

(h) _____ Agent has verbally informed purchaser or lessee-purchaser of the possible presence of dangerous levels of lead in paint, plaster, putty or other structural materials and his or her obligations to bring a property into compliance with the Massachusetts Lead Law - either through full deleading or interim control - if it was built before 1978 and a child under six years old resides or will reside in the property.

Certification of Accuracy

The following parties have reviewed the information above and certify, to the best of their knowledge, that the information they have provided is true and accurate.

DocuSigned by: Lawrence Marshall 0E8D0A84B748420...	1/25/2014		
Seller Lawrence Marshall	Date	Seller	Date
Purchaser	Date	Purchaser	Date
DocuSigned by: Mark Bishop F3735B25B2FD47F...	1/24/2014		
Agent Mark Bishop	Date	Agent	Date

Address of Property / Unit 27-29 Oxford Street, Haverhill, MA 01830

CLPPP Form 94-3, 6/30/94, Rev. 12/10

MASSFORMS™ Statewide Standard Real Estate Forms ©1999, 2006, 2010 MASSACHUSETTS ASSOCIATION OF REALTORS®

Produced with ZipForm® by zipLogix 18070 Fifteen Mile Road, Fraser, Michigan 48026 www.zipLogix.com

M & M
LEAD INSPECTIONAL SERVICES, INC.
~ Servicing All of Massachusetts ~

LETTER OF FULL DELEADING COMPLIANCE

DATE: October 25, 2007

Mike Sice

27 Oxford Street

Haverhill, MA01930

Dear Mike Sice :

This letter is to certify that I re-inspected your property located at 29 Oxford Street, apartment no. N/A , and relevant common areas, in the City or Town of Haverhill,
for full deleading compliance on October 5, 2007, and on that date those surfaces cited in the initial inspection report of November 14, 2006 were found to be in full compliance with Massachusetts General Laws, Chapter 111, Section 197, and 105 CMR 460.000: Regulations for Lead Poisoning Prevention and Control. Dust samples were taken and found to be within acceptable limits.

Massachusetts law does not require the abatement or containment of all residential lead paint. The residential premises or dwelling unit and relevant common areas shall remain in compliance only as long as there continues to be no peeling, chipping or flaking lead paint or other accessible leaded materials, as long as coverings and/or encapsulants forming an effective barrier over such paint or other leaded materials remain in place, and as long as surfaces reversed to correct lead hazards remain reversed and securely in place. The law grants you a 30-day maintenance period to repair deteriorated lead paint or detached coverings over such paint, and to clean up, during which time this Letter remains valid.

The reverse side of this letter indicates the authorized person(s) who performed deleading on the property and a general summary of the methods used. A complete reinspection report is attached to this letter, which specifies how and on what date each surface was brought into compliance. Do not lose these documents.

To the best of my knowledge, the cost of the legally required deleading is $ 5,000.00 .

Sincerely,

Gary Marcelle

Inspector
M3169
DPH License Number

137 Beacon Street • Lawrence, MA 01843
Phone 617-737-2514 • 978-685-4172 • Fax 978-685-9062
www.mmlead.com

ADDRESS 29 Oxford Street, Haverhill, MA

Inspection and Deleading History

Initial inspection done on: 11/14/2006 by Gary Marciello License #M3169

Reoccupancy reinspection, if needed, done on: N/A by _____ License#_____

Final Deleading reinspection done on: 10/05/2007 by Gary Marciello License # M3169

Deleading Contractor: Jose Rivera – I.D.I. Construction - License #: DC0001782

Deleading methods: Scraping, Demolition, Power sanding, Caustics, Heat gun, Replacement, Covering, Liquid encapsulation, Other _____

Work was done in the following rooms: Kitchen, 5, 6

Work was done on the following types of components: Replace doors

Start Date: 12/08/2006 Finish Date: 01/16/2007 Cost: $5,000.00

Lead-safe renovator: _____ License#: _____
Moderate risk owner/agent: _____ Authorization #: _____

Deleading Methods: Replacement, Making intact (interior), Making intact (exterior), Covering, Liquid encapsulation

Work was done in the following rooms: _____

Work was done on the following types of components: _____

Start Date: __/__/__ Finish Date: __/__/__ Cost: $_____ (Doesn't Include Owner's Labor)

Low-risk owner/agent: _____ Authorization #: _____

Deleading methods: Covering, Liquid encapsulation, Capping baseboards, Replacement (ONLY doors, cabinet doors, shutters, shelves not affixed, drawers, windows on hinges)

Work was done in the following rooms: _____

Work was done on the following types of components: _____

Start Date __/__/__ Finish Date: __/__/__ Cost: $_____ (Doesn't Include Owner's Labor)

Should you have any questions about this letter, call the Department of Public Health at 1-800-532-9571.

Lead Inspection / Risk Assessment Report

M & M
LEAD INSPECTIONAL SERVICES, INC.
— Servicing all of Massachusetts —
Phone (617) 737-2514, (978) 685-4172 • Fax (978) 685-9062

Method Used:
☐ Na_2S Exp. Date _____
☒ X-Ray Fluorescence
Model RMD Serial # 1129

St.# 29 Address Oxford St Apt.

City Haverhill Zip Code 01830

Owner Name: Mike Sice

Owner Address: 27 Oxford St
Haverhill MA 01830 - 978-374-7703

Client Name (if different from owner):

Client Address:

Single Family	
Multi Family	2
# Units	
Condominium	
Day Care	

Key:

	Inspection		Deleading	Other
A/M	Accessible/Mouthable	CAP	Capped	
CAP	Capped	COV	Covered	
COV	Covered	DIP	Dipped	
INT	Intact	ENC	Encapsulated	
L	Loose	MI	Made Intact	
M/I	Moveable/Impacted	PRE	Prepared	
MET	Metal	REM	Removed	
NA	Not Accessible	REP	Replaced	
NC	No Coating	REV	Reversed	
NEG	Negative	SCR	Scraped	
POS	Positive	VR	Vinyl Replacement	
VR	Vinyl Replacement			

☒ Comprehensive Inspection (Y/N)

Comments:

Floor# 1



A (Street Side)

Floor# _____



A (Street Side)

Pb (lead) greater than or equal to 1.0mg/cm^2 with x-ray fluorescence or positive with Na_2S is **Dangerous.**

INSP. DATE
1/14/06

Y Lead Hazards? (Y or N)

Gary Marcello
Inspector (print)

Gary Marcello
Signature

M3169
Lic.#

R.A. DATE

☐ Urgent Lead Hazards? (Y or N)

Risk Assessor (print)

Signature

Lic.#

Property Address:

Page 12 of 15

(St.) 29 9th Fond. St (City) Haverhill (Apt/Floor) 2 (Zip) _____

INSPECTION ACTIVITY KEY		PASS OR FAIL	EXAMPLE BOX
1. Reocc. Reinspection	6. Interim Control	P Pass	☐ inspection activity number
2. Reinspection	7. Recertification	F Fail	☐ pass or fail
3. Dust Taken	8. Post Compliance Assess. Determ.		
4. Dust received	9. Maintained Comp		
5. Full Delead Compliance	10. Restored Comp		

☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐ ☐ ☐	Inspector _____ Lic # _____

DATES	COMMENTS:

EXPLANATION OF LEAD INSPECTION / RISK ASSESSMENT REPORT FORM COLUMNS

page provides general information needed to understand the lead inspection/risk assessment report. However, you should speak the inspector/risk assessor before you start to do any work on your home.

)E

Refers to A, B, C, or D side of the building or room. See the diagram on the cover sheet. The "A" side of the building or room is the side facing the street that gives the property its address (usually, it is the front of the building). Keeping your back to this street, from the "A" side move clockwise to the "B" side on your left, the "C" side opposite you, and the "D" side to the right.

:ATION/ :FACE

Refers to the building component(s) being tested. Some surfaces may be made up of more than one part. For example, "Baseboard" may refer to four separate pieces of wood (one on each wall), but is still considered one surface.

.D

The actual lead result. Each surface tested must have a result recorded in the "Lead" column.

- A number shows that the surface was tested with an XRF analyzer. A number (or average number) equal to or greater than 1.0 mg/cm^2 is a dangerous level of lead.
- A "pos" or "neg" shows that the surface was tested with sodium sulfide. "Pos" means that there is a dangerous level of lead.
- "N/A" means that the inspector was not able to test the surface. Unless the owner can get a sample to test, the inspector must assume the surface contains lead and require it to be deleaded, if necessary.
- "Metal" means that a metal surface was not tested and only needs to be intact. However, metal handrails, metal window sills, and metal railing caps, need to be deleaded if they are equal to or greater than 1.0 mg/cm^2, "pos," or is "N/A."

?E OF ZARD

Not all lead paint must be deleaded. This column tells you IF and WHY a surface needs deleading. The deleading standards below may not apply for Interim Controls. Speak to your risk assessor for more information.

- "M/I" circled means that the surface is a moveable/impacted surface and must be deleaded in its entirety.
- "A/M" circled means that the surface is "accessible mouthable" and must be deleaded to a minimum of five feet high, four inches in from the edge or corner.
- "L" circled means that the surface is loose and must, at minimum, be made intact.
- If more than one choice is circled, the rules for deleading may change depending upon what method of deleading you choose. Speak to the inspector for more information.
- "N/A" means the inspector was unable to determine if the surface was loose or intact. The person doing the deleading must check this surface and follow all the rules for deleading. Speak to the inspector for more information.
- If nothing is circled or marked "N/A" then it is likely the surface does not need deleading. Speak to the inspector for more information.

HAZ?

This column is only completed during a risk assessment. A risk assessment is an evaluation of a home's suitability for Interim Controls. **Only a licensed risk assessor can do a risk assessment, not all inspectors are risk assessors.** If "Y" is circled, then this surface is considered an "Urgent Lead Hazard" and some type of deleading work is required to qualify for Interim Control.

ATE

The date the licensed risk assessor determines the surface meets the standards for Interim Control.

IETH

The deleading method or structural repair done to qualify the surface for Interim Control. Refer to the deleading codes key on the cover page.

EAD E

The date that the lead inspector or risk assessor reinspects the surface and finds that it has been successfully deleaded for full compliance.

EAD H

The deleading method used to bring a surface into full compliance. Refer to deleading codes in the Key on the cover page of the inspection report.

LUDED FACES

The amount of loose paint on a surface as measured by the lead inspector. "N/A" means that the inspector was not able to measure the loose paint, but has determined it is more than the cut-off for moderate risk making intact. Surfaces listed here can only be made intact by a licensed deleader. Note there are still other low and moderate-risk deleading activities, such as covering, that may be done by someone who is not a licensed deleader.

TEST ILTS

This information is found on the exterior pages. If your property receives certain federal funding, soil testing may be required. There is also a space for the risk assessor to indicate amount of bare soil, laboratory results, method of remediation, and the date of remediation. Check with your funding agency for more information.

Gary Marcello | M3169 | Gary Marcello | 11/14/06 | Page 4 Of 15

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 290 Ford ST | Apt # FL1 | City Haverhill

ROOM 1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	—	A/M L N/A	Y				
A B C D	Baseboards	00	A/M L N/A	Y				
A B C D	Chair Rail	—	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
C	Door	—	A/M L N/A	Y				
C	Door Casing	0.1	A/M L N/A	Y				
C	Door Jamb	0.2	A/M L N/A	Y				
C	Threshold	—	A/M L N/A	Y				
D	Door	0.2	A/M L N/A	Y				
D	Door Casing	01	A/M L N/A	Y				
D	Door Jamb	01	A/M L N/A	Y				
D	Threshold	—	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
A	Window Sill	0.2	M/I A/M L N/A	Y				
A	Win Apron	01	A/M L N/A	Y				
A	Win Casing	00	A/M L N/A	Y				
A	Header Stop	00	M/I A/M L N/A	Y				
A	Int Stops	01	M/I A/M L N/A	Y				
A	Win Int Sash	VR	M/I A/M L N/A	Y				
A	Exterior Sill	VR	M/I L N/A	Y				
A	Part Bead	VR	M/I L N/A	Y				
A	Blind Stop	VR	M/I L N/A	Y				
A	Win Ext Sash	VR	M/I L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A 2	Window Sill	01	M/I A/M L N/A	Y				
A 2	Win Apron	01	A/M L N/A	Y				
A 2	Win Casing	01	A/M L N/A	Y				
A 2	Header Stop	01	M/I A/M L N/A	Y				
A 2	Int Stops	00	M/I A/M L N/A	Y				
A 2	Win Int Sash	VR	M/I A/M L N/A	Y				
A 2	Exterior Sill	VR	M/I A/M L N/A	Y				
A 2	Part Bead	VR	M/I A/M L N/A	Y				
A 2	Blind Stop	VR	M/I A/M L N/A	Y				
A 2	Win Ext Sash	VR	M/I A/M L N/A	Y				
A 3	Window Sill	01	M/I A/M L N/A	Y				
A 3	Win Apron	00	A/M L N/A	Y				
A 3	Win Casing	00	A/M L N/A	Y				
A 3	Header Stop	01	M/I A/M L N/A	Y				
A 3	Int Stops	01	M/I A/M L N/A	Y				
A 3	Win Int Sash	VR	M/I A/M L N/A	Y				
A 3	Exterior Sill	VR	M/I A/M L N/A	Y				
A 3	Part Bead	VR	M/I A/M L N/A	Y				
A 3	Blind Stop	VR	M/I A/M L N/A	Y				
A 3	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

DE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | 93169 | [signature] | 11/14/06
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 29 Ox Ford St. | Apt # FL 1 | City Haverhill

ROOM | CONT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls		A/M L N/A	Y				
A B C D	Low Walls		A/M L N/A	Y				
A B C D	Baseboards		A/M L N/A	Y				
A B C D	Chair Rail		A/M L N/A	Y				
	Radiator		A/M L N/A	Y				
	Floor		A/M L N/A	Y				
	Ceiling		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill	01	M/I A/M L N/A	Y				
	Win Apron	00	A/M L N/A	Y				
	Win Casing	01	A/M L N/A	Y				
B	Header Stop	01	M/I A/M L N/A	Y				
	Int Stops	0-1	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I L N/A	Y				
	Part Bead	VR	M/I L N/A	Y				
	Blind Stop	VR	M/I L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

OMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

DE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCELLO | PA3169 | [signature] | 11/14/06
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 29 OXFORD ST. Apt # FL1 City HAVERHILL

ROOM 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.3	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	02	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	0.0	A/M L N/A	Y				
	Floor	0.1	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
D	Door	/	A/M L N/A	Y				
D	Door Casing	02	A/M L N/A	Y				
D	Door Jamb	01	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
A	Door	/	A/M L N/A	Y				
A	Door Casing	00	A/M L N/A	Y				
A	Door Jamb	01	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
C 3	Door	00	A/M L N/A	Y	UP			
C 3	Door Casing	00	A/M L N/A	Y				
C 3	Door Jamb	0.1	A/M L N/A	Y				
C 3	Threshold	/	A/M L N/A	Y				
C 2	Door	00	A/M L N/A	Y	UP=00			
C 2	Door Casing	00	A/M L N/A	Y				
C 2	Door Jamb	01	A/M L N/A	Y	FRAME			
C 2	Threshold	/	A/M L N/A	Y				
3	Window Sill	02	M/I A/M L N/A	Y				
3	Win Apron	01	A/M L N/A	Y				
3	Win Casing	00	A/M L N/A	Y				
3	Header Stop	01	M/I A/M L N/A	Y				
3	Int Stops	0.1	M/I A/M L N/A	Y				
3	Win Int Sash	VR	M/I A/M L N/A	Y				
3	Exterior Sill	VR	M/I L N/A	Y				
3	Part Bead	VR	M/I L N/A	Y				
3	Blind Stop	VR	M/I L N/A	Y				
3	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B 2	Window Sill	02	M/I A/M L N/A	Y				
B 2	Win Apron	00	A/M L N/A	Y				
B 2	Win Casing	00	A/M L N/A	Y				
B 2	Header Stop	01	M/I A/M L N/A	Y				
B 2	Int Stops	01	M/I A/M L N/A	Y				
B 2	Win Int Sash	VR	M/I A/M L N/A	Y				
B 2	Exterior Sill	VR	M/I A/M L N/A	Y				
B 2	Part Bead	VR	M/I A/M L N/A	Y				
B 2	Blind Stop	VR	M/I A/M L N/A	Y				
B 2	Win Ext Sash	VR	M/I A/M L N/A	Y				
B 3	Window Sill	01	M/I A/M L N/A	Y				
B 3	Win Apron	02	A/M L N/A	Y				
B 3	Win Casing	01	A/M L N/A	Y				
B 3	Header Stop	01	M/I A/M L N/A	Y				
B 3	Int Stops	01	M/I A/M L N/A	Y				
B 3	Win Int Sash	VR	M/I A/M L N/A	Y				
B 3	Exterior Sill	VR	M/I A/M L N/A	Y				
B 3	Part Bead	VR	M/I A/M L N/A	Y				
B 3	Blind Stop	VR	M/I A/M L N/A	Y				
B 3	Win Ext Sash	VR	M/I A/M L N/A	Y				
C	Closet Door	01	A/M L N/A	Y	HATCH			
C	Cl Casing	/	A/M L N/A	Y	INT DOOR			
C	Closet Jamb	/	A/M L N/A	Y	FRAME			
C	Closet Walls	C 00	A/M L N/A	Y				
C	Cl Baseboard	/	A/M L N/A	Y				
C	Closet Pole	/	A/M L N/A	Y				
C	Closet Shelf	01	A/M L N/A	Y				
C	Cl Supports	0.1	A/M L N/A	Y				
C	Closet Floor	~	A/M L N/A	Y				
C	Closet Ceiling	C 00	A/M L N/A	Y	PAINT			
C	CASE	01	M/I A/M L N/A	Y				
1	JAM	01	M/I A/M L N/A	Y				
C	LOW CASE	01	M/I A/M L N/A	Y				
	INT DOOR	01	M/I A/M L N/A	Y				
	WALL	00	M/I A/M L N/A	Y				
	FLOOR	01	M/I A/M L N/A	Y				
	SHELVE	01	M/I A/M L N/A	Y	SHOP 00			

MMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcelli | 093169 | [signature] | 11/14/06 | Page 37 of 15

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 19 Oxford ST. | Apt # FL1 | City Haverhill

ROOM 3

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	0.0	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
C 1	Door	01	A/M L N/A	Y				
C 1	Door Casing	00	A/M L N/A	Y				
C 1	Door Jamb	02	A/M L N/A	Y				
C 1	Threshold	/	A/M L N/A	Y				
C 2	Door	01	A/M L N/A	Y				
C 2	Door Casing	01	A/M L N/A	Y				
C 2	Door Jamb	00	A/M L N/A	Y				
C 2	Threshold	/	A/M L N/A	Y				
A	Door	00	A/M L N/A	Y				
A	Door Casing	01	A/M L N/A	Y				
A	Door Jamb	0.1	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D 1	Window Sill	0.1	M/I A/M L N/A	Y				
D 1	Win Apron	0.0	A/M L N/A	Y				
D 1	Win Casing	01	A/M L N/A	Y				
D 1	Header Stop	00	M/I A/M L N/A	Y				
D 1	Int Stops	01	M/I A/M L N/A	Y				
D 1	Win Int Sash	VR	M/I A/M L N/A	Y				
D 1	Exterior Sill	VR	M/I L N/A	Y				
D 1	Part Bead	VR	M/I L N/A	Y				
D 1	Blind Stop	VR	M/I L N/A	Y				
D 1	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D 2	Window Sill	0.2	M/I A/M L N/A	Y				
D 2	Win Apron	0.1	A/M L N/A	Y				
D 2	Win Casing	0.1	A/M L N/A	Y				
D 2	Header Stop	00	M/I A/M L N/A	Y				
D 2	Int Stops	0.2	M/I A/M L N/A	Y				
D 2	Win Int Sash	VR	M/I A/M L N/A	Y				
D 2	Exterior Sill	VR	M/I A/M L N/A	Y				
D 2	Part Bead	VR	M/I A/M L N/A	Y				
D 2	Blind Stop	VR	M/I A/M L N/A	Y				
D 2	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
C	Closet Door	01	A/M L N/A	Y				
C	Cl Casing	02	A/M L N/A	Y				
C	Closet Jamb	0.2	A/M L N/A	Y				
C	Closet Walls	01	A/M L N/A	Y				
C	Cl Baseboard	0.2	A/M L N/A	Y				
C	Closet Pole	01	A/M L N/A	Y				
C	Closet Shelf	0.2	A/M L N/A	Y				
C	Cl Supports	01	A/M L N/A	Y				Pipe NC
C	Closet Floor	00	A/M L N/A	Y				
C	Closet Ceiling	NA	A/M L N/A	Y				
A	Closet		M/I A/M L N/A	Y				
	Door	02	M/I A/M L N/A	Y				
	Case	0.1	M/I A/M L N/A	Y				Walls 01
	Jam	04	M/I A/M L N/A	Y				Shelf 02
	Base	0.2	M/I A/M L N/A	Y				Supp 01
	Ceil	0.1	M/I A/M L N/A	Y				
	Floor	01	M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

DE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | 193169 | [signature] | 11/14/16
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 290 Xford St. | Apt # FL1 | City Haverhill

ROOM 4

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	01	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	00	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	0.4	A/M L N/A	Y				
A	Door Casing	0.4	A/M L N/A	Y				
A	Door Jamb	01	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B	Door	0.2	A/M L N/A	Y				
B	Door Casing	03	A/M L N/A	Y				
B	Door Jamb	04	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D	Window Sill	0.2	M/I A/M L N/A	Y				
D	Win Apron	01	A/M L N/A	Y				
D	Win Casing	00	A/M L N/A	Y				
D	Header Stop	02	M/I A/M L N/A	Y				
1	Int Stops	01	M/I A/M L N/A	Y				
1	Win Int Sash	VR	M/I A/M L N/A	Y				
1	Exterior Sill	VR	M/I L N/A	Y				
1	Part Bead	VR	M/I L N/A	Y				
1	Blind Stop	VR	M/I L N/A	Y				
1	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Window Sill	0.0	M/I A/M L N/A	Y				
D	Win Apron	0.0	A/M L N/A	Y				
D	Win Casing	01	A/M L N/A	Y				
D	Header Stop	0.2	M/I A/M L N/A	Y				
2	Int Stops	01	M/I A/M L N/A	Y				
2	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I A/M L N/A	Y				
2	Part Bead	VR	M/I A/M L N/A	Y				
2	Blind Stop	VR	M/I A/M L N/A	Y				
2	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
B	Closet Door	0.2	A/M L N/A	Y				
B	Cl Casing	01	A/M L N/A	Y				
B	Closet Jamb	0.0	A/M L N/A	Y				
B	Closet Walls	03	A/M L N/A	Y				
B	Cl Baseboard	0.2	A/M L N/A	Y				
B	Closet Pole	00	A/M L N/A	Y				
B	Closet Shelf	01	A/M L N/A	Y				
B	Cl Supports	00	A/M L N/A	Y				
B	Closet Floor	Rug	A/M L N/A	Y				
B	Closet Ceiling	NA	A/M L N/A	Y	Pipe PVC			
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

DE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marciello M3169 Gary Marciello 11/14/06

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic# Signature Date

Address of Property 29 Oxford St. Apt # FL 1 City Haverhill

KITCHEN

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	00	A/M L N/A	Y				
A B C D	Low Walls	CW	A/M L N/A	Y				
A B C D	Baseboards	00	A/M L N/A	Y				
A B C D	Chair Rail	01	A/M L N/A	Y				
	Radiator	0.1	A/M L N/A	Y				
	Floor	LINO	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
D	Door	0.2	A/M L N/A	Y				
D	Door Casing	01	A/M L N/A	Y				
D	Door Jamb	00	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
A 1	Door	01	A/M L N/A	Y				
A 1	Door Casing	00	A/M L N/A	Y				
A 1	Door Jamb	02	A/M L N/A	Y				
A 1	Threshold	00	A/M L N/A	Y				
C	Window Sill	01	M/I A/M L N/A	Y				
C	Win Apron	00	A/M L N/A	Y				
C	Win Casing	01	A/M L N/A	Y				
C	Header Stop	00	M/I A/M L N/A	Y				
C	Int Stops	01	M/I A/M L N/A	Y				
C	Win Int Sash	VR	M/I A/M L N/A	Y				
C	Exterior Sill	VR	M/I A/M L N/A	Y				
C	Part Bead	VR	M/I A/M L N/A	Y				
C	Blind Stop	VR	M/I A/M L N/A	Y				
C	Win Ext Sash	VR	M/I A/M L N/A	Y				
B D	Up Cab Frame	01	A/M L N/A	Y				
B D	Up Cab Door	00	A/M L N/A	Y	INT	OC		
B D	Up Cab Walls	CW	A/M L N/A	Y				
B D	Up Cab Shlvs	01	A/M L N/A	Y				
B D	Supports	00	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	COMMENTS	DELEAD DATE	DELEAD METHOD
B 1 2	Window Sill	01	M/I A/M L			
B 1 2	Apron	00	A/M L			
B 1 2	Win Casing	00	A/M L			
B 1 2	Win Header	01	M/I A/M L	CASE		
B 1 2	Int Stops	00	M/I A/M L	CRANK Unit		
B 1 2	Win Int Sash	02	M/I A/M L			
B 1 2	Exterior Sill	01	M/I L			
B 1 2	Part Bead	00	M/I L			
B 1 2	Blind Stop	00	M/I L			
B 1 2	Win Ext Sash	00	M/I L			
A	Closet Door	0-2	A/M L			
A	Cl Casing	0.3	A/M L			
A	Closet Jamb	0.1	A/M L			
A	Closet Walls	0.8	A/M L			
A	Cl Baseboard	4.2	A/M L			
A	Closet Pole	/	A/M L			
A	Closet Shelf	0-2	A/M L			
A	Cl Supports	9.4	A/M L			
A	Closet Floor	LINO	L			
A	Closet Ceiling	NA	L			
	Up Cab Frame		A/M L			
	Cab Door		A/M L			
	Up Cab Walls		A/M L			
	Up Cab Shlvs		A/M L			
	Supports		A/M L			
B	Low Cab Fram	01	A/M L			
B	Cab Door	00	A/M L	FNT - 0.1		
B	Low Cab Walls	00	A/M L			
B	Low Cab Shlvs	01	A/M L			
B	Supports	/	A/M L			
B	Drawers	01	A/M L			
A 2	~~Door~~	~~01~~				
A 2	CASE	00				
A 2	JAM	00				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	DATE	METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	DATE	METHOD

Gary Marciello M3169 Gary Marciello 11/14/06

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic# Signature Date

Address of Property 29 01 Ford St. Apt # FL1 City Haverhill

BATHROOM

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	9.9	A/M L N/A	Y				
A B C D	Low Walls	T/C	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	T/C	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
B	Door	01	A/M L N/A	Y				
B	Door Casing	02	A/M L N/A	Y				
B	Door Jamb	01	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
	Door	/	A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D	Window Sill	01	M/I A/M L N/A	Y		CR-2		
D	Win Apron	01	A/M L N/A	Y		CRANKOUT		
D	Win Casing	00	A/M L N/A	Y				
D	Header Stop	01	M/I A/M L N/A	Y				
D	Int Stops	01	M/I A/M L N/A	Y		>5-1		
D	Win Int Sash	NA	M/I A/M L N/A	Y				
D	Exterior Sill	NA	M/I A/M L N/A	Y				
D	Part Bead	NA	M/I A/M L N/A	Y				
D	Blind Stop	NA	M/I A/M L N/A	Y				
D	Win Ext Sash	NA	M/I A/M L N/A	Y				
	Up Cab Frame		A/M L N/A	Y				
	Up Cab Door		A/M L N/A	Y				
	Up Cab Walls		A/M L N/A	Y				
	Up Cab Shlvs		A/M L N/A	Y				
	Supports		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Low Cab Fram		A/M L N/A	Y				
	Low Cab Door		A/M L N/A	Y				
	Low Cab Walls		A/M L N/A	Y				
	Low Cab Shlvs		A/M L N/A	Y				
	Supports		A/M L N/A	Y				
	Drawers		A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Closet Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Clos Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

IDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD
	LI/RA RepBath	1/17/02		

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCIELLO M3169 Mary Marciello 11/14/06
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 29 OXFORD ST Apt # FL 1 & 2 City HAVERHILL

STAIRCASE REAR TO BASEMENT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y	WALL CASE		0.2	
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y	SILL PLATE		0.1	
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	N.C	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
B	Door	0.1	A/M L N/A	Y	FL1			
B	Door Casing	0.0	A/M L N/A	Y				
B	Door Jamb	0.1	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
D	Door	0.0	A/M L N/A	Y	ON LANDING			
D	Door Casing	8.2	A/M L N/A	Y				
D	Door Jamb	2.2	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door		A/M L N/A	Y				
	CI Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	CI Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	CI Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Newel Post	/	A/M L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower rail	/	A/M L N/A	Y				
	Treads	0.0	A/M L N/A	Y				
	Risers	0.2	A/M L N/A	Y				
	Stringer	0.1	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing	0.1	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCiello m3169 Gary Marciello 11/14/06
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 19 OXFORD ST. Apt # FL1 City HAVERHILL

HALLWAY FRONT ENTRY

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	01	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	01	A/M L N/A	Y				
A	Door Casing	01	A/M L N/A	Y				
A	Door Jamb	01	A/M L N/A	Y				
A	Threshold	01	A/M L N/A	Y				
B	Door	01	A/M L N/A	Y				
B	Door Casing	02	A/M L N/A	Y				
B	Door Jamb	01	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
D	Door	01	A/M L N/A	Y				
D	Door Casing	02	A/M L N/A	Y				
D	Door Jamb	01	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		L N/A	Y				
	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
	Win Int Sash		M/I L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Cl Ceiling		A/M L N/A	Y				
D	Closet Door	02	A/M L N/A	Y				
D	Cl Casing	02	A/M L N/A	Y				
D	Closet Jamb	01	A/M L N/A	Y				
D	Closet Walls	01	A/M L N/A	Y				
D	Cl Baseboard	01	A/M L N/A	Y				
D	Closet Pole	02	A/M L N/A	Y				
D	Closet Shelf	01	A/M L N/A	Y				
D	Cl Supports	00	A/M L N/A	Y				
D	Closet Floor	01	A/M L N/A	Y				
D	Cl Ceiling	00	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCiello m 3169 Gary Marciello 11/14/06
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 29 OXFORD ST. Apt # FL1 City HAVERHILL

HALLWAY

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	0.1	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	01	A/M L N/A	Y				
A	Door Casing	02	A/M L N/A	Y				
A	Door Jamb	01	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B	Door	/	A/M L N/A	Y				
B	Door Casing	0.2	A/M L N/A	Y				
B	Door Jamb	01	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
C	Door	02	A/M L N/A	Y				
C	Door Casing	0.3	A/M L N/A	Y				
C	Door Jamb	02	A/M L N/A	Y				
C	Threshold	/	A/M L N/A	Y				
D	Door	02	A/M L N/A	Y				
D	Door Casing	01	A/M L N/A	Y				
D	Door Jamb	01	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		L N/A	Y				
	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
	Win Int Sash		M/I L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Cl Ceiling		A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Cl Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

DE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCIELLO M3169 Gary Marciello 11/14/02
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 29 OXFORD ST. Apt # FLR City HUDSON HILL

STAIRCASE REAR TO BASEMENT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y	WALLPAPER		02	
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards		A/M L N/A	Y	2.11	PLANE	01	
A B C D	Chair Rail		A/M L N/A	Y				
	Radiator		A/M L N/A	Y				
	Floor	N/C	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
B	Door	.21	A/M L N/A	Y	FLR			
B	Door Casing	0	A/M L N/A	Y				
B	Door Jamb	.21	A/M L N/A	Y				
B	Threshold		A/M L N/A	Y				
D	Door	0.0	A/M L N/A	Y	OK LANDING			
D	Door Casing	2.3	A/M L N/A	Y				
D	Door Jamb	.22	A/M L N/A	Y				
D	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door		A/M L N/A	Y				
	CI Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	CI Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	CI Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Newel Post		A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower rail		A/M L N/A	Y				
	Treads	0.2	A/M L N/A	Y				
	Risers	0.2	A/M L N/A	Y				
	Stringer	.51	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing	0.1	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marecchi — PM3169 — Gary Marecchi — 11/14/06
Inspector (print) — Lic # — Signature — Date

Risk Assessor (print) — Lic # — Signature — Date

Address of Property 22 Oxford St. — Apt # FL 1 & 2 — City Haverhill

ROOM Laundry Basement

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	Ab	A/M L N/A	Y		BM-4	±5	
A B C D	Low Walls	—	A/M L N/A	Y				
A B C D	Baseboards	—	A/M L N/A	Y	Surface	07		
A B C D	Chair Rail	—	A/M L N/A	Y				
	Radiator	—	A/M L N/A	Y				
	Floor	NL	A/M L N/A	Y				
	Ceiling	Ab	A/M L N/A	Y	Surface			
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill	—	M/I A/M L N/A	Y				
	Win Apron	—	A/M L N/A	Y				
3	Win Casing	—	A/M L N/A	Y	Surface			
	Header Stop	—	M/I A/M L N/A	Y				
	Int Stops	—	M/I A/M L N/A	Y				
	Win Int Sash	01	M/I A/M L N/A	Y				
	Exterior Sill	—	M/I L N/A	Y				
	Part Bead	—	M/I L N/A	Y				
	Blind Stop	—	M/I L N/A	Y				
	Win Ext Sash	—	M/I L N/A	Y				

MMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill	—	M/I A/M L N/A	Y				
	Win Apron	—	A/M L N/A	Y				
C	Win Casing	—	A/M L N/A	Y	Surface			
	Header Stop	—	M/I A/M L N/A	Y				
	Int Stops	—	M/I A/M L N/A	Y				
	Win Int Sash	01	M/I A/M L N/A	Y				
	Exterior Sill	—	M/I A/M L N/A	Y				
	Part Bead	—	M/I A/M L N/A	Y				
	Blind Stop	—	M/I A/M L N/A	Y				
	Win Ext Sash	—	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	[illegible]	Ab	M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

E	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Lead Inspection / Risk Assessment Report

M & M
LEAD INSPECTIONAL SERVICES, INC.
— Servicing all of Massachusetts —
Phone (617) 737-2514, (978) 685-4172 • Fax (978) 685-9062

Method Used:
☐ Na_2S Exp. Date _____
☒ X-Ray Fluorescence
Model RMD Serial # 1139

St.# 27 Address 0xford ST Apt. 2

City Haverhill Zip Code 01830

Owner Name: Mike Sice

Owner Address: 27 oxford st
Haverhill. MA 01830 / 978-374-7705

Client Name (if different from owner):

Client Address:

Single Family	___
Multi Family	✓
# Units	2
Condominium	___
Day Care	___

Key:

	Inspection		Deleading	Other
A/M	Accessible/Mouthable	CAP	Capped	
CAP	Capped	COV	Covered	
COV	Covered	DIP	Dipped	
INT	Intact	ENC	Encapsulated	
L	Loose	MI	Made Intact	
M/I	Moveable/Impacted	PRE	Prepared	
MET	Metal	REM	Removed	
NA	Not Accessible	REP	Replaced	
NC	No Coating	REV	Reversed	
NEG	Negative	SCR	Scraped	
POS	Positive	VR	Vinyl Replacement	
VR	Vinyl Replacement			

☒ Comprehensive Inspection (Y/N)

Comments: Basement storage

Floor# 2



Floor# 1



Pb (lead) greater than or equal to 1.0mg/cm² with x-ray fluorescence or positive with Na_2S is **Dangerous.**

INSP. DATE	Lead Hazards? (Y or N)	Inspector (print)	Signature	Lic.#
6/2/06	Y	Gary Mitchell	Gary Mitchell	M369

R.A. DATE	Urgent Lead Hazards? (Y or N)	Risk Assessor (print)	Signature	Lic.#

INSPECTION HISTORY PAGE

Page ____ of ____

Property Address:
(St.) _____ (City) _____ (Apt/Floor) ____ (Zip) _____

INSPECTION ACTIVITY KEY		PASS OR FAIL
1. Reocc. Reinspection	6. Interim Control	P Pass
2. Reinspection	7. Recertification	F Fail
3. Dust Taken	8. Post Compliance Assess. Determ.	
4. Dust received	9. Maintained Comp	
5. Full Delead Compliance	10. Restored Comp	

EXAMPLE BOX

☐ inspection activity number
☐ pass or fail

☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____
☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____	☐☐☐☐☐☐	☐ ☐	Inspector _____ Lic # _____

DATES	COMMENTS:

EXPLANATION OF LEAD INSPECTION / RISK ASSESSMENT REPORT FORM COLUMNS

page provides general information needed to understand the lead inspection/risk assessment report. However, you should speak he inspector/risk assessor before you start to do any work on your home.

E

Refers to A, B, C, or D side of the building or room. See the diagram on the cover sheet. The "A" side of the building or room is the side facing the street that gives the property its address (usually, it is the front of the building). Keeping your back to this street, from the "A" side move clockwise to the "B" side on your left, the "C" side opposite you, and the "D" side to the right.

ATION/ FACE

Refers to the building component(s) being tested. Some surfaces may be made up of more than one part. For example, "Baseboard" may refer to four separate pieces of wood (one on each wall), but is still considered one surface.

D

The actual lead result. Each surface tested must have a result recorded in the "Lead" column.

- A number shows that the surface was tested with an XRF analyzer. A number (or average number) equal to or greater than 1.0 mg/cm^2 is a dangerous level of lead.
- A "pos" or "neg" shows that the surface was tested with sodium sulfide. "Pos" means that there is a dangerous level of lead.
- "N/A" means that the inspector was not able to test the surface. Unless the owner can get a sample to test, the inspector must assume the surface contains lead and require it to be deleaded, if necessary.
- "Metal" means that a metal surface was not tested and only needs to be intact. However, metal handrails, metal window sills, and metal railing caps, need to be deleaded if they are equal to or greater than 1.0 mg/cm^2, "pos," or is "N/A."

E OF ARD

Not all lead paint must be deleaded. This column tells you IF and WHY a surface needs deleading. The deleading standards below may not apply for Interim Controls. Speak to your risk assessor for more information.

- "M/I" circled means that the surface is a moveable/impacted surface and must be deleaded in its entirety.
- "A/M" circled means that the surface is "accessible mouthable" and must be deleaded to a minimum of five feet high, four inches in from the edge or corner.
- "L" circled means that the surface is loose and must, at minimum, be made intact.
- If more than one choice is circled, the rules for deleading may change depending upon what method of deleading you choose. Speak to the inspector for more information.
- "N/A" means the inspector was unable to determine if the surface was loose or intact. The person doing the deleading must check this surface and follow all the rules for deleading. Speak to the inspector for more information.
- If nothing is circled or marked "N/A" then it is likely the surface does not need deleading. Speak to the inspector for more information.

HAZ?

This column is only completed during a risk assessment. A risk assessment is an evaluation of a home's suitability for Interim Controls. Only a licensed risk assessor can do a risk assessment, not all inspectors are risk assessors. If "Y" is circled, then this surface is considered an "Urgent Lead Hazard" and some type of deleading work is required to qualify for Interim Control.

ATE

The date the licensed risk assessor determines the surface meets the standards for Interim Control.

IETH

The deleading method or structural repair done to qualify the surface for Interim Control. Refer to the deleading codes key on the cover page.

EAD E

The date that the lead inspector or risk assessor reinspects the surface and finds that it has been successfully deleaded for full compliance.

EAD H

The deleading method used to bring a surface into full compliance. Refer to deleading codes in the Key on the cover page of the inspection report.

LUDED FACES

The amount of loose paint on a surface as measured by the lead inspector. "N/A" means that the inspector was not able to measure the loose paint, but has determined it is more than the cut-off for moderate risk making intact. Surfaces listed here can only be made intact by a licensed deleader. Note there are still other low and moderate-risk deleading activities, such as covering, that may be done by someone who is not a licensed deleader.

TEST ULTS

This information is found on the exterior pages. If your property receives certain federal funding, soil testing may be required. There is also a space for the risk assessor to indicate amount of bare soil, laboratory results, method of

GARY MANCUSO 193169 [signature] 11/14/06 Page 4 Of ___

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 21 UX Ford St. Apt # FL 3 City Worcester

ROOM 1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y				
A B C D	Low Walls		A/M L N/A	Y				
A B C D	Baseboards	00	A/M L N/A	Y				
A B C D	Chair Rail	—	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
C	Door	—	A/M L N/A	Y				
C	Door Casing	00	A/M L N/A	Y				
C	Door Jamb	01	A/M L N/A	Y				
C	Threshold	—	A/M L N/A	Y				
D	Door	01	A/M L N/A	Y				
D	Door Casing	00	A/M L N/A	Y				
D	Door Jamb	01	A/M L N/A	Y				
D	Threshold	—	A/M L N/A	Y				
	Door	—	A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
A	Window Sill	01	M/I A/M L N/A	Y				
A	Win Apron	00	A/M L N/A	Y				
A	Win Casing	01	A/M L N/A	Y				
A	Header Stop	00	M/I A/M L N/A	Y				
A	Int Stops	01	M/I A/M L N/A	Y				
A	Win Int Sash	NA	M/I A/M L N/A	Y				
A	Exterior Sill	NA	M/I A/M L N/A	Y				
A	Part Bead	NA	M/I A/M L N/A	Y				
A	Blind Stop	NA	M/I A/M L N/A	Y				
A	Win Ext Sash	NA	M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Window Sill	01	M/I A/M L N/A	Y				
B	Win Apron	01	A/M L N/A	Y				
B	Win Casing	01	A/M L N/A	Y				
B	Header Stop	00	M/I A/M L N/A	Y				
B	Int Stops	01	M/I A/M L N/A	Y				
B	Win Int Sash	NA	M/I A/M L N/A	Y				
B	Exterior Sill	NA	M/I A/M L N/A	Y				
B	Part Bead	NA	M/I A/M L N/A	Y				
B	Blind Stop	NA	M/I A/M L N/A	Y				
B	Win Ext Sash	NA	M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | 093169 | Gary Marcello | 11/14/06 | Page 2 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 37 Oxford St. | Apt # #2 | City Haverhill

ROOM 1 Cont.

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls		A/M L N/A	Y				
A B C D	Low Walls		A/M L N/A	Y				
A B C D	Baseboards		A/M L N/A	Y				
A B C D	Chair Rail		A/M L N/A	Y				
	Radiator		A/M L N/A	Y				
	Floor		A/M L N/A	Y				
	Ceiling		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I L N/A	Y				
	Part Bead		M/I L N/A	Y				
	Blind Stop		M/I L N/A	Y				
	Win Ext Sash		M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCELLO | PA3169 | [signature] | 11/14/06 | Page 6 of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 27 OXFORD ST. | Apt # FL 2 | City HAVERHILL

ROOM 2

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.0	A/M L N/A	Y				
A B C D	Baseboards	0.1	A/M L N/A	Y				
A B C D	Chair Rail	0.1	A/M L N/A	Y				
	Radiator	0.0	A/M L N/A	Y				
	Floor	0.1	A/M L N/A	Y				
	Ceiling	VR	A/M L N/A	Y				
A	Door	—	A/M L N/A	Y				
	Door Casing	0.1	A/M L N/A	Y				
	Door Jamb	0.0	A/M L N/A	Y				
	Threshold	—	A/M L N/A	Y				
D	Door	—	A/M L N/A	Y				
	Door Casing	0.1	A/M L N/A	Y				
	Door Jamb	0.0	A/M L N/A	Y				
	Threshold	—	A/M L N/A	Y				
C	Door	0.0	A/M L N/A	Y	Match Up			
3	Door Casing	0.1	A/M L N/A	Y				
	Door Jamb	0.1	A/M L N/A	Y				
	Threshold	—	A/M L N/A	Y				
C	Door	0.1	A/M L N/A	Y	Match Lower			
2	Door Casing	0.0	A/M L N/A	Y				
	Door Jamb	0.1	A/M L N/A	Y				
	Threshold	—	A/M L N/A	Y				
B	Window Sill	0.1	M/I A/M L N/A	Y				
1	Win Apron	0.1	A/M L N/A	Y				
	Win Casing	0.0	A/M L N/A	Y				
	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
	Win Int Sash	V.	M/I A/M L N/A	Y				
	Exterior Sill		M/I L N/A	Y				
	Part Bead	VR	M/I L N/A	Y				
	Blind Stop	VR	M/I L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Window Sill	0.1	M/I A/M L N/A	Y				
2	Win Apron	0.1	A/M L N/A	Y				
	Win Casing	0.0	A/M L N/A	Y				
	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I A/M L N/A	Y				
	Part Bead	VR	M/I A/M L N/A	Y				
	Blind Stop	VR	M/I A/M L N/A	Y				
	Win Ext Sash	VR	M/I A/M L N/A	Y				
B	Window Sill	0.1	M/I A/M L N/A	Y				
3	Win Apron	0.1	A/M L N/A	Y				
	Win Casing	0.0	A/M L N/A	Y				
	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.0	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I A/M L N/A	Y				
	Part Bead	VR	M/I A/M L N/A	Y				
	Blind Stop	VR	M/I A/M L N/A	Y				
	Win Ext Sash	VR	M/I A/M L N/A	Y				
C	Closet Door	0.1	A/M L N/A	Y	Match			
2	Cl Casing	—	A/M L N/A	Y				
	Closet Jamb	—	A/M L N/A	Y	Fair	Paint	0.0	
	Closet Walls	0.0	A/M L N/A	Y	Low			
	Cl Baseboard	—	A/M L N/A	Y	Fair	Paint	0.0	
	Closet Pole	—	A/M L N/A	Y	Dust	Stick	0.1	
	Closet Shelf	0.0	A/M L N/A	Y	Sag		0.0	
	Cl Supports	0.1	A/M L N/A	Y	Fair	Paint	0.1	
	Closet Floor	—	A/M L N/A	Y				
	Closet Ceiling	—	A/M L N/A	Y				
C	Case	0.1	M/I A/M L N/A	Y				
1	Trim	0.0	M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCELLI | 093169 | [signature] | 11/14/06
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 22 OXFORD ST | Apt # FL 2 | City HAVERHILL

ROOM 3

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	0.1	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	0.2	A/M L N/A	Y				
	Floor	0.0	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
C 1	Door	0.1	A/M L N/A	Y				
	Door Casing	0.4	A/M L N/A	Y				
	Door Jamb	0.2	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
C 2	Door	0.1	A/M L N/A	Y				
	Door Casing	0.2	A/M L N/A	Y				
	Door Jamb	0.1	A/M L N/A	Y				
	Threshold	0.0	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D 1	Window Sill	0.0	M/I A/M L N/A	Y				
	Win Apron	0.1	A/M L N/A	Y				
	Win Casing	0.1	A/M L N/A	Y				
	Header Stop	0.0	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I L N/A	Y				
	Part Bead	VR	M/I L N/A	Y				
	Blind Stop	VR	M/I L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D 2	Window Sill	0.0	M/I A/M L N/A	Y				
	Win Apron	0.0	A/M L N/A	Y				
	Win Casing	0.2	A/M L N/A	Y				
	Header Stop	0.1	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I A/M L N/A	Y				
	Part Bead	VR	M/I A/M L N/A	Y				
	Blind Stop	VR	M/I A/M L N/A	Y				
	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
C	Closet Door	0.0	A/M L N/A	Y				
	Cl Casing	0.4	A/M L N/A	Y				
	Closet Jamb	0.2	A/M L N/A	Y				
	Closet Walls	0.1	A/M L N/A	Y				
	Cl Baseboard	NA	A/M L (N/A)	Y				
	Closet Pole	NC	A/M L N/A	Y				
	Closet Shelf	0.0	A/M L N/A	Y				
	Cl Supports	0.2	A/M L N/A	Y				
	Closet Floor	0.1	A/M L N/A	Y				
	Closet Ceiling	0.0	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCiello m3169 Gary Marciello 11/14/06

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 27 Oxford St. Apt # FL 2 City Haverhill

HALLWAY

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.1	A/M L N/A	Y				
A B C D	Low Walls	0.0	A/M L N/A	Y				
A B C D	Baseboards	0.2	A/M L N/A	Y				
A B C D	Chair Rail	0.2	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	0.1	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	0.0	A/M L N/A	Y				
A	Door Casing	0.2	A/M L N/A	Y				
A	Door Jamb	0.3	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B	Door	/	A/M L N/A	Y				
B	Door Casing	0.2	A/M L N/A	Y				
B	Door Jamb	0.3	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
C	Door	0.2	A/M L N/A	Y				
C	Door Casing	0.1	A/M L N/A	Y				
C	Door Jamb	0.1	A/M L N/A	Y				
C	Threshold	/	A/M L N/A	Y				
D	Door	0.1	A/M L N/A	Y				
D	Door Casing	0.0	A/M L N/A	Y				
D	Door Jamb	0.1	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		L N/A	Y				
	Header Stop		M/I L N/A	Y				
	Int Stops		M/I L N/A	Y				
	Win Int Sash		M/I L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Cl Ceiling		A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Cl Ceiling		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marciello m3169 Gary Marciello 11/14/01 Page 9 Of ___

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic# Signature Date

Address of Property 30 Oxford St Apt # FL 2 City Haverhill, MA

BATHROOM

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	00	A/M L N/A	Y				
A B C D	Low Walls	—	A/M L N/A	Y				
A B C D	Baseboards	0.1	A/M L N/A	Y				
A B C D	Chair Rail	—	A/M L N/A	Y				
	Radiator	0.0	A/M L N/A	Y				
	Floor	N/a	A/M L N/A	Y				
	Ceiling	NR	A/M L N/A	Y				
B	Door	0.1	A/M L N/A	Y				
B	Door Casing	0.1	A/M L N/A	Y				
B	Door Jamb	0.2	A/M L N/A	Y				
B	Threshold	—	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D	Window Sill		M/I A/M L N/A	Y				
D	Win Apron		A/M L N/A	Y				
D	Win Casing		A/M L N/A	Y				
D	Header Stop		M/I A/M L N/A	Y				
D	Int Stops		M/I A/M L N/A	Y		F		
D	Win Int Sash		M/I A/M L N/A	Y		J		
D	Exterior Sill		M/I A/M L N/A	Y				
D	Part Bead		M/I A/M L N/A	Y				
D	Blind Stop		M/I A/M L N/A	Y				
D	Win Ext Sash		M/I A/M L N/A	Y				
C	Up Cab Frame	0.1	A/M L N/A	Y				
C	Up Cab Door	0.1	A/M L N/A	Y	T	VT	-0.1	
C	Up Cab Walls	00	A/M L N/A	Y				
C	Up Cab Shlvs	0.1	A/M L N/A	Y				
C	Supports	—	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Low Cab Fram	0.1	A/M L N/A	Y				
C	Low Cab Door	0.1	A/M L N/A	Y	T	VT	-0.1	
C	Low Cab Walls	0.1	A/M L N/A	Y				
C	Low Cab Shlvs	00	A/M L N/A	Y				
C	Supports	—	A/M L N/A	Y				
C	Drawers	00	A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Closet Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Clos Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				
			M/I A/M L NA	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD
	LI/RA RepBath	1/17/02		

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcelli | M3169 | [signature] | 11/14/01 | Page 1 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 37 Lexford St. | Apt # FL 2 | City Hawkins

ROOM 4

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.3	A/M L N/A	Y				
A B C D	Low Walls	—	A/M L N/A	Y				
A B C D	Baseboards	0.2	A/M L N/A	Y				
A B C D	Chair Rail	—	A/M L N/A	Y				
	Radiator	0.1	A/M L N/A	Y				
	Floor	0.1	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	0.1	A/M L N/A	Y				
A	Door Casing	0.2	A/M L N/A	Y				
A	Door Jamb	0.2	A/M L N/A	Y				
A	Threshold	—	A/M L N/A	Y				
B	Door	0.0	A/M L N/A	Y				
B	Door Casing	0.0	A/M L N/A	Y				
B	Door Jamb	0.2	A/M L N/A	Y				
B	Threshold	0.1	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D	Window Sill	0.1	M/I A/M L N/A	Y				
D	Win Apron	0.2	A/M L N/A	Y				
D	Win Casing	0.3	A/M L N/A	Y				
D	Header Stop	0.1	M/I A/M L N/A	Y				
D	Int Stops	0.2	M/I A/M L N/A	Y				
D	Win Int Sash	VR	M/I A/M L N/A	Y				
D	Exterior Sill	VR	M/I L N/A	Y				
D	Part Bead	VR	M/I L N/A	Y				
D	Blind Stop	VR	M/I L N/A	Y				
D	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Window Sill	0.2	M/I A/M L N/A	Y				
D	Win Apron	0.1	A/M L N/A	Y				
D	Win Casing	0.1	A/M L N/A	Y				
D	Header Stop	0.2	M/I A/M L N/A	Y				
D	Int Stops	0.2	M/I A/M L N/A	Y				
D	Win Int Sash	VR	M/I A/M L N/A	Y				
D	Exterior Sill	VR	M/I A/M L N/A	Y				
D	Part Bead	VR	M/I A/M L N/A	Y				
D	Blind Stop	VR	M/I A/M L N/A	Y				
D	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
B	Closet Door	0.2	A/M L N/A	Y				
B	Cl Casing	0.3	A/M L N/A	Y				
B	Closet Jamb	0.2	A/M L N/A	Y				
B	Closet Walls	0.1	A/M L N/A	Y				
B	Cl Baseboard	NA	A/M L N/A	Y				
B	Closet Pole	—	A/M L N/A	Y				
B	Closet Shelf	0.2	A/M L N/A	Y				
B	Cl Supports	0.2	A/M L N/A	Y	Pipe Pl.			
B	Closet Floor	0.1	A/M L N/A	Y				
B	Closet Ceiling	NA	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marciello m3169 Gary Marciello 11/14/01

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic# Signature Date

Address of Property 170 Oxford St Apt # FL2 City Haverhill

KITCHEN

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y				
A B C D	Low Walls	Cov	A/M L N/A	Y				
A B C D	Baseboards	01	A/M L N/A	Y				
A B C D	Chair Rail	01	A/M L N/A	Y				
	Radiator	Cov	A/M L N/A	Y				
	Floor	4-INP	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
D	Door	01	A/M L N/A	Y				
D	Door Casing	01	A/M L N/A	Y				
D	Door Jamb	02	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
A	Door	/	A/M L N/A	Y				
A	Door Casing	01	A/M L N/A	Y				
A	Door Jamb	02	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B 1 2	Window Sill	01	M/I A/M L N/A	Y				
B 1 2	Win Apron	/	A/M L N/A	Y				
B 1 2	Win Casing	01	A/M L N/A	Y				
B 1 2	Header Stop	01	M/I A/M L N/A	Y				
B 1 2	Int Stops	00	M/I A/M L N/A	Y		Case Crankout		
B 1 2	Win Int Sash	0.0	M/I A/M L N/A	Y				
B 1 2	Exterior Sill	02	M/I A/M L N/A	Y				
B 1 2	Part Bead	/	M/I A/M L N/A	Y				
B 1 2	Blind Stop	/	M/I A/M L N/A	Y				
B 1 2	Win Ext Sash	01	M/I A/M L N/A	Y				
B D	Up Cab Frame	01	A/M L N/A	Y				
B D	Up Cab Door	02	A/M L N/A	Y		INT - 01		
B D	Up Cab Walls	01	A/M L N/A	Y				
B D	Up Cab Shlvs	00	A/M L N/A	Y				
B D	Supports	00	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	COMMENTS	DELEAD DATE	DELEAD METHOD
C 1-4	Window Sill	02	M/I A/M L	C2+3		Fixed
C 1-4	Apron	01	A/M L	Case Crankout		
C 1-4	Win Casing	01	A/M L			
C 1-4	Win Header	01	M/I A/M L			
C 1-4	Int Stops	00	M/I A/M L			
C 1-4	Win Int Sash	01	M/I A/M L			
C 1-4	Exterior Sill	01	M/I L			
C 1-4	Part Bead	/	M/I L			
C 1-4	Blind Stop	/	M/I L			
C 1-4	Win Ext Sash	01	M/I L			
	Closet Door		A/M L			
	Cl Casing		A/M L			
	Closet Jamb		A/M L			
	Closet Walls		A/M L			
	Cl Baseboard		A/M L			
	Closet Pole		A/M L			
	Closet Shelf		A/M L			
	Cl Supports		A/M L			
	Closet Floor		L			
	Closet Ceiling		L			
	Up Cab Frame		A/M L			
	Cab Door		A/M L			
	Up Cab Walls		A/M L			
	Up Cab Shlvs		A/M L			
	Supports		A/M L			
B	Low Cab Fram	01	A/M L			
B	Cab Door	00	A/M L	INT - 0.1		
B	Low Cab Walls	00	A/M L			
B	Low Cab Shlvs	01	A/M L			
B	Supports	/	A/M L			
B	Drawers	0.1	A/M L			

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	DATE	METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	DATE	METHOD

Gary Marcello M3169 Gary Marcello 11/14/06 Page 12 of ___

Inspector (print) Lic # Signature Date

Address of Lead Inspection 27 OXFORD ST Apt # FL2 City HAVERHILL

PORCH C FL2 Enclosed Exterior

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Siding	0.7		L	WALLS		
	Corner Boards	/		L			
	Upper Trim	/		L			
	Ceiling	NC		L			
	Joists	NA		L			
A	Door	0/	A/M	L			
	Storm Door	/	A/M	L			
	Door Casing	9.9	A/M	L			
	Door Jamb	9.9	A/M	L			
	Threshold	0/	A/M	L			
	Kickplate	/	A/M	L			
	Door	\	A/M	L			
	Storm Door		A/M	L			
	Door Casing		A/M	L			
	Door Jamb		A/M	L			
	Threshold		A/M	L			
	Kickplate		A/M	L			
B 1 2	Window Sill	Rem	A/M	L			
	Win Casing	Rem	A/M	L			
	Window Sash	STOR	A/M	L			
	Mullions	/	A/M	L			
C 1-3	Window Sill	Rem	A/M	L			
	Win Casing	Rem	A/M	L			
	Window Sash	STOR	A/M	L			
	Mullions	/	A/M	L			
D 1 2	Window Sill	Rem	A/M	L			
	Win Casing	Rem	A/M	L			
	Window Sash	STOR	A/M	L			
	Mullions	/	A/M	L			
	Window Sill	\	A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			

COMMENTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Support Clmns	/	A/M	L			
	Newel post	/	A/M	L			
	Railing Cap	/	A/M	L			
	Handrail	/	A/M	L			
	Balusters	/	A/M	L			
	Lower Rail	/	A/M	L			
	Treads	/	A/M	L			
	Risers	/	A/M	L			
	Stringer	/	A/M	L			
	Low Walls	/	A/M	L			
	Lattice	/	A/M	L			
	Low Trim	/		L			
	Floor	RUG		L			
	Threshold	/	A/M	L			
B	2 x 4	NC			SUPPORT		
C							
D							
	Low Frame	NC					
A	Shelf	5.4	(A/M)				
	Supp	NC					

COMMENTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

Gary Marciello M3164 Gary Marciello 11/14/06
Inspector (print) Lic # Signature Date

Page 1 Of 3

Risk Assessor (print) Lic # Signature Date

Address of Property 27 Oxford St Apt # FL 2 City Haverhill

STAIRCASE H 2nd To 3rd

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	02	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	01	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	01	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A	Door	01	A/M L N/A	Y	FL 2			
A	Door Casing	00	A/M L N/A	Y				
A	Door Jamb	00	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B	Door	02	A/M L N/A	Y		FL 2		
B	Door Casing	01	A/M L N/A	Y				
B	Door Jamb	00	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
B	Door	01	A/M L N/A	Y		FL 3		
B	Door Casing	0.6	A/M L N/A	Y				
B	Door Jamb	01	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
C	Door	02	A/M L N/A	Y	FL 3			
C	Door Casing	01	A/M L N/A	Y				
C	Door Jamb	00	A/M L N/A	Y				
C	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door		A/M L N/A	Y				
	CI Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	CI Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	CI Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Newel Post	/	A/M L N/A	Y				
	Railing Cap	02	A/M L N/A	Y				
	Handrail	01	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower rail	/	A/M L N/A	Y				
	Treads	01	A/M L N/A	Y				
	Risers	01	A/M L N/A	Y				
	Stringer	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing		A/M L N/A	Y				
	Wallcase	01	M/I A/M L N/A	Y	FL 2			
	Wallcase	01	M/I A/M L N/A	Y	ON STAIRS			
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | PB3169 | [signature] | 11/14/02 | Page 1 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 21 Oxford St | Apt # FL 1 | City Haverhill

ROOM 5

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	01	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y	Mold Above		01	
	Floor	Rug	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
	Door	0-0	A/M L N/A	Y				
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	01	A/M L N/A	Y				
	Threshold	0.0	A/M L N/A	Y				
	Door	01	A/M L N/A	Y				
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	01	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill	02	M/I A/M L N/A	Y				
	Win Apron	01	A/M L N/A	Y				
	Win Casing	01	A/M L N/A	Y				
	Header Stop	01	M/I A/M L N/A	Y				
	Int Stops	00	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I L N/A	Y				
	Part Bead	VR	M/I L N/A	Y				
	Blind Stop	VR	M/I L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill	02	M/I A/M L N/A	Y				
	Win Apron	0.3	A/M L N/A	Y				
	Win Casing	01	A/M L N/A	Y				
	Header Stop	01	M/I A/M L N/A	Y				
	Int Stops	0.1	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I A/M L N/A	Y				
	Part Bead	VR	M/I A/M L N/A	Y				
	Blind Stop	VR	M/I A/M L N/A	Y				
	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y				
	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
	Win Int Sash	/	M/I A/M L N/A	Y				
	Exterior Sill	/	M/I A/M L N/A	Y				
	Part Bead	/	M/I A/M L N/A	Y				
	Blind Stop	/	M/I A/M L N/A	Y				
	Win Ext Sash	/	M/I A/M L N/A	Y				
	Closet Door	02	A/M L N/A	Y				
	Cl Casing	0.3	A/M L N/A	Y				
	Closet Jamb	0.2	A/M L N/A	Y				
	Closet Walls	0.3	A/M L N/A	Y				
	Cl Baseboard	NA	A/M L N/A	Y				
	Closet Pole	NC	A/M L N/A	Y				
	Closet Shelf	02	A/M L N/A	Y				
	Cl Supports	0.1	A/M L N/A	Y				
	Closet Floor	0.1	A/M L N/A	Y				
	Closet Ceiling	0.1	A/M L N/A	Y				
B	Shelf	01	M/I A/M L N/A	Y				
	Desk	00	M/I A/M L N/A	Y				
	Frame	0.1	M/I A/M L N/A	Y				
	Drawer	0.1	M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | 93169 | [signature] | 11/16/02 | Page 1 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 370 Ford St. | Apt # F-4 | City Ludlow

ROOM 7 Kitchen

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	0.1	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	0.2	A/M L N/A	Y				
	Floor	T/C	A/M L N/A	Y				
	Ceiling	N/A	A/M L N/A	Y				
D	Door	/	A/M L N/A	Y				
D	Door Casing	1.1	A/M L N/A	Y				
D	Door Jamb	0.1	A/M L N/A	Y				
D	Threshold	/	A/M L N/A	Y				
A	Door	0.2	A/M L N/A	Y				
A	Door Casing	0.1	A/M L N/A	Y				
A	Door Jamb	0.1	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
C	Window Sill	0.1	M/I A/M L N/A	Y				
C	Win Apron	0.2	A/M L N/A	Y				
C	Win Casing	0.1	A/M L N/A	Y				
C	Header Stop	0.2	M/I A/M L N/A	Y				
C	Int Stops	0.1	M/I A/M L N/A	Y				
C	Win Int Sash	VR	M/I A/M L N/A	Y				
C	Exterior Sill	VR	M/I L N/A	Y				
C	Part Bead	VR	M/I L N/A	Y				
C	Blind Stop	VR	M/I L N/A	Y				
C	Win Ext Sash	VR	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
2	Window Sill	0.1	M/I A/M L N/A	Y				
2	Win Apron	0.1	A/M L N/A	Y				
2	Win Casing	0.2	A/M L N/A	Y				
2	Header Stop	0.1	M/I A/M L N/A	Y				
2	Int Stops	0.1	M/I A/M L N/A	Y				
2	Win Int Sash	VR	M/I A/M L N/A	Y				
2	Exterior Sill	VR	M/I A/M L N/A	Y				
2	Part Bead	VR	M/I A/M L N/A	Y				
2	Blind Stop	VR	M/I A/M L N/A	Y				
2	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
A	Closet Door	0.1	A/M L N/A	Y				
A	Cl Casing	0.1	A/M L N/A	Y				
A	Closet Jamb	0.0	A/M L N/A	Y				
A	Closet Walls	0.1	A/M L N/A	Y				
A	Cl Baseboard	/	A/M L N/A	Y				
A	Closet Pole	/	A/M L N/A	Y				
A	Closet Shelf	0.2	A/M L N/A	Y				
A	Cl Supports	0.1	A/M L N/A	Y				
A	Closet Floor	0.0	A/M L N/A	Y				
A	Closet Ceiling	N/A	A/M L N/A	Y				
A	Cl Frame	0.1	M/I A/M L N/A	Y				
B	Frame	0.0	M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Mancuso | 993169 | Gary Mancuso | 1/14/06 | Page 6 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 37 OXFORD ST. | Apt # FL2 | City LAWRENCE

ROOM 6

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	01	A/M L N/A	Y		SIP	IP 01	
A B C D	Low Walls	/	A/M L N/A	Y	B WALL	Bench Rem		
A B C D	Baseboards	/	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	01	A/M L N/A	Y				
	Floor	RUG	A/M L N/A	Y				
	Ceiling	NA	A/M L N/A	Y				
A 1	Door	01	A/M L N/A	Y				
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	02	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
A 2	Door	01	A/M L N/A	Y	To STORAGE			
	Door Casing	/	A/M L N/A	Y				
	Door Jamb	/	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
C 1	Door	99	A/M L N/A	Y		To STORAGE		
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	01	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
C 3	Door	01	A/M L N/A	Y	Rear STAIRS			
	Door Casing	02	A/M L N/A	Y				
	Door Jamb	01	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
B	Window Sill	01	M/I A/M L N/A	Y				
	Win Apron	02	A/M L N/A	Y				
	Win Casing	02	A/M L N/A	Y				
	Header Stop	01	M/I A/M L N/A	Y				
	Int Stops	01	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I L N/A	Y				
	Part Bead	VR	M/I L N/A	Y				
	Blind Stop	VR	M/I L N/A	Y				
	Win Ext Sash	VR	M/I L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Window Sill	02	M/I A/M L N/A	Y	IN D		CAP	
	Win Apron	01	A/M L N/A	Y				
	Win Casing	01	A/M L N/A	Y				
	Header Stop	01	M/I A/M L N/A	Y				
	Int Stops	01	M/I A/M L N/A	Y				
	Win Int Sash	VR	M/I A/M L N/A	Y				
	Exterior Sill	VR	M/I A/M L N/A	Y				
	Part Bead	VR	M/I A/M L N/A	Y				
	Blind Stop	VR	M/I A/M L N/A	Y				
	Win Ext Sash	VR	M/I A/M L N/A	Y				
	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
D	Closet Door	04	A/M L N/A	Y				
	Cl Casing	01	A/M L N/A	Y				
	Closet Jamb	02	A/M L N/A	Y				
	Closet Walls	01	A/M L N/A	Y				
	Cl Baseboard	/	A/M L N/A	Y				
	Closet Pole	01	A/M L N/A	Y				
	Closet Shelf	01	A/M L N/A	Y				
	Cl Supports	01	A/M L N/A	Y	LOW SUP 01			
	Closet Floor	RUG	A/M L N/A	Y				
	Closet Ceiling	NA	A/M L N/A	Y				
D	DOOR	01	M/I A/M L N/A	Y				
2	CASE	01	M/I A/M L N/A	Y				
	JAMB	01	M/I A/M L N/A	Y				
D	DRAWS	01	M/I A/M L N/A	Y				
1	LOW FRAME	01	M/I A/M L N/A	Y				
2			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCELLI 993169 [signature] 11/14/02 Page 11 Of ___

Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 27 OXFORD ST Apt # FL2 City HAVERHILL

ROOM L CRAT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls		A/M L N/A	Y				
A B C D	Low Walls		A/M L N/A	Y				
A B C D	Baseboards		A/M L N/A	Y				
A B C D	Chair Rail		A/M L N/A	Y				
	Radiator		A/M L N/A	Y				
	Floor		A/M L N/A	Y				
	Ceiling		A/M L N/A	Y				
D 1	Door	99	A/M L N/A	Y				
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	00	A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D 3	Door	9.5	A/M L N/A	Y				
	Door Casing	01	A/M L N/A	Y				
	Door Jamb	00	A/M L N/A	Y				
	Threshold	/	A/M L N/A	Y				
P 2	Door	01	A/M L N/A	Y				
	Door Casing	00	A/M L N/A	Y				
	Door Jamb	01	A/M L N/A	Y				
	Threshold	\	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I L N/A	Y				
	Part Bead		M/I L N/A	Y				
	Blind Stop		M/I L N/A	Y				
	Win Ext Sash		M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
D	BLANKET		M/I A/M L N/A	Y				
1	SHELF 00		M/I A/M L N/A	Y				
D	WALL		M/I A/M L N/A	Y				
	CASE 01		M/I A/M L N/A	Y				
A	SHELF 01		M/I A/M L N/A	Y				
	SUPP 02		M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

GARY MARCIELLO M3169 Gary Marciello 11/11/06
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 370 FORD ST Apt # FL 2 City HAVERHILL

STAIRCASE C 2nd TO 3rd

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	02	A/M L N/A	Y				
A B C D	Low Walls	CW	A/M L N/A	Y		R49		
A B C D	Baseboards	02	A/M L N/A	Y				
A B C D	Chair Rail	01	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	R49	A/M L N/A	Y				
	Ceiling	01	A/M L N/A	Y				
A	Door	01	A/M L N/A	Y	FL 3			
A	Door Casing	02	A/M L N/A	Y				
A	Door Jamb	01	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
B	Door	/	A/M L N/A	Y	FL 3			
B	Door Casing	01	A/M L N/A	Y				
B	Door Jamb	02	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
B 1	Door	01	A/M L N/A	Y	FL 2			
B 1	Door Casing	02	A/M L N/A	Y				
B 1	Door Jamb	01	A/M L N/A	Y				
B 1	Threshold	/	A/M L N/A	Y				
B 2	Door	01	A/M L N/A	Y	FL 2			
B 2	Door Casing	CC	A/M L N/A	Y				
B 2	Door Jamb	CC	A/M L N/A	Y				
B 2	Threshold	/	A/M L N/A	Y				
C	Door	01	A/M L N/A	Y	FL 2			
C	Door Casing	CC	A/M L N/A	Y				
C	Door Jamb	CC	A/M L N/A	Y				
C	Threshold	/	A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Closet Door	01	A/M L N/A	Y	FL 2			
B	CI Casing	/	A/M L N/A	Y				
B	Closet Jamb	01	A/M L N/A	Y				
B	Closet Walls	CW	A/M L N/A	Y				
B	CI Baseboard	/	A/M L N/A	Y				
B	Closet Pole	CC	A/M L N/A	Y				
B	Closet Shelf	01	A/M L N/A	Y				
B	CI Supports	CC	A/M L N/A	Y				
B	Closet Floor	LINK	A/M L N/A	Y	PIPE		06	
B	Closet Ceiling	NA	A/M L N/A	Y				
	Newel Post	/	A/M L N/A	Y				
	Railing Cap	01	A/M L N/A	Y				
	Handrail	02	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower rail	/	A/M L N/A	Y				
	Treads	R49	A/M L N/A	Y	LEAD WAIVER			
	Risers	R49	A/M L N/A	Y				
	Stringer	/	A/M L N/A	Y	WALLS		06	
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing		A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcella | PA3169 | Gary Marcella | 11/14/06 | Page ___ Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 270 X Ford ST. | Apt # FL142 | City Haverhill

ROOM Laundry Basement

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	NL	A/M L N/A	Y		Brush	# Stroke	
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y	5.11.06		0.7	
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	NL	A/M L N/A	Y				
	Ceiling	NL	A/M L N/A	Y	JOIST	NL		
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
B	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y	L W Laundry			
	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
	Win Int Sash	01	M/I A/M L N/A	Y				
	Exterior Sill	/	M/I L N/A	Y				
	Part Bead	/	M/I L N/A	Y				
	Blind Stop	/	M/I L N/A	Y				
	Win Ext Sash	/	M/I L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Window Sill	/	M/I A/M L N/A	Y				
	Win Apron	/	A/M L N/A	Y				
	Win Casing	/	A/M L N/A	Y	11.6.06			
	Header Stop	/	M/I A/M L N/A	Y				
	Int Stops	/	M/I A/M L N/A	Y				
	Win Int Sash	01	M/I A/M L N/A	Y				
	Exterior Sill	/	M/I A/M L N/A	Y				
	Part Bead	/	M/I A/M L N/A	Y				
	Blind Stop	/	M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Chimney	NL	M/I A/M L N/A	Y	11.6.06	Brush		
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marciello M3169 Dan Mauriello 11/14/16 Page 20 of ___

Inspector (print) Lic # Signature Date

Address of Lead Inspection 27 Oxford St. Apt # FL2 City Haverhill

PORCH A FL2 Enclosed Ext

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Siding	Cov		L	Panel		
	Corner Boards	—		L	Low wall Panel		
	Upper Trim	—		L			
	Ceiling	Plas		L			
	Joists	—		L			
C	Door	01	A/M	L			
	Storm Door	—	A/M	L			
	Door Casing	—	A/M	L			
	Door Jamb	Cov	A/M	L	Panel		
	Threshold	06	A/M	L			
	Kickplate	—	A/M	L			
	Door		A/M	L			
	Storm Door		A/M	L			
	Door Casing		A/M	L			
	Door Jamb		A/M	L			
	Threshold		A/M	L			
	Kickplate		A/M	L			
C	Window Sill	99	A/M	L			
	Win Casing	NA	A/M	L			
	Window Sash	NA	A/M	L			
	Mullions	—	A/M	L			
A 1-6	Window Sill	01	A/M	L			
	Win Casing	Cov	A/M	L	Panel		
	Window Sash	ALU	A/M	L	Jalsie		
	Mullions	—	A/M	L			
B 1 D 1-3	Window Sill	01	A/M	L			
	Win Casing	Cov	A/M	L	Panel		
	Window Sash	Alu	A/M	L	Jalsie		
	Mullions	—	A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			

COMMENTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Support Cmns	Cov	A/M	L			
	Newel post	—	A/M	L			
	Railing Cap	—	A/M	L			
	Handrail	—	A/M	L			
	Balusters	—	A/M	L			
	Lower Rail	—	A/M	L			
	Treads	—	A/M	L			
	Risers	—	A/M	L			
	Stringer	—	A/M	L			
	Low Walls	—	A/M	L			
	Lattice	—	A/M	L			
	Low Trim	—		L			
	Floor	Alu		L			
	Threshold	—	A/M	L			

COMMENTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

Gary Marciello m3169 Gary Marciello 11/14/02
Inspector (print) Lic # Signature Date

Risk Assessor (print) Lic # Signature Date

Address of Property 27 Oxford St Apt # FL 1 City Haverhill

STAIRCASE A 1ST TO 2nd

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.2	A/M L N/A	Y				
A B C D	Low Walls	/	A/M L N/A	Y				
A B C D	Baseboards	0.0	A/M L N/A	Y				
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	0.1	A/M L N/A	Y				
	Floor	0.0	A/M L N/A	Y				
	Ceiling	NT	A/M L N/A	Y				
A	Door	0.2	A/M L N/A	Y		FL 1		
A	Door Casing	0.1	A/M L N/A	Y				
A	Door Jamb	0.0	A/M L N/A	Y				
A	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
D	Window Sill	0.1	M/I A/M L N/A	Y		On Landing		
D	Win Apron	0.2	A/M L N/A	Y				
D	Win Casing	0.1	A/M L N/A	Y				
D	Header Stop	0.0	M/I A/M L N/A	Y				
D	Int Stops	0.1	M/I A/M L N/A	Y				
D	Win Int Sash	VR	M/I A/M L N/A	Y				
D	Exterior Sill	VR	M/I A/M L N/A	Y				
D	Part Bead	VR	M/I A/M L N/A	Y				
D	Blind Stop	VR	M/I A/M L N/A	Y				
D	Win Ext Sash	VR	M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door		A/M L N/A	Y				
	Cl Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	Cl Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	Cl Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Newel Post	/	A/M L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	0.1	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower rail	/	A/M L N/A	Y				
	Treads	0.2	A/M L N/A	Y				
	Risers	0.1	A/M L N/A	Y				
	Stringer	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing		A/M L N/A	Y				
Wallcase		0.0	M/I A/M L N/A	Y		On Stair		
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marciello M3169 Gary Marciello 11/14/06
Inspector (print) Lic # Signature Date

Page ___ Of ___

Risk Assessor (print) Lic # Signature Date

Address of Property 270 OXFORD ST Apt # FL 1+2 City HAVERHILL

STAIRCASE REAR TO BASEMENT

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A B C D	Up Walls	0.0	A/M L N/A	Y	WALL	CASE	0.2	
A B C D	Low Walls	0.1	A/M L N/A	Y				
A B C D	Baseboards	/	A/M L N/A	Y	SILL	PLATE	0.1	
A B C D	Chair Rail	/	A/M L N/A	Y				
	Radiator	/	A/M L N/A	Y				
	Floor	N/C	A/M L N/A	Y				
	Ceiling	0.1	A/M L N/A	Y				
B	Door	0.1	A/M L N/A	Y	FLR			
B	Door Casing	0.2	A/M L N/A	Y				
B	Door Jamb	0.1	A/M L N/A	Y				
B	Threshold	/	A/M L N/A	Y				
D	Door	0.0	A/M L N/A	Y	ON LANDING			
D	Door Casing	8.2	A/M L N/A	Y				STR
D	Door Jamb	2.2	A/M L N/A	Y				STR
D	Threshold	/	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Window Sill		M/I A/M L N/A	Y				
	Win Apron		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Header Stop		M/I A/M L N/A	Y				
	Int Stops		M/I A/M L N/A	Y				
	Win Int Sash		M/I A/M L N/A	Y				
	Exterior Sill		M/I A/M L N/A	Y				
	Part Bead		M/I A/M L N/A	Y				
	Blind Stop		M/I A/M L N/A	Y				
	Win Ext Sash		M/I A/M L N/A	Y				

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
	Closet Door	/	A/M L N/A	Y				
	CI Casing		A/M L N/A	Y				
	Closet Jamb		A/M L N/A	Y				
	Closet Walls		A/M L N/A	Y				
	CI Baseboard		A/M L N/A	Y				
	Closet Pole		A/M L N/A	Y				
	Closet Shelf		A/M L N/A	Y				
	CI Supports		A/M L N/A	Y				
	Closet Floor		A/M L N/A	Y				
	Closet Ceiling		A/M L N/A	Y				
	Newel Post	/	A/M L N/A	Y				
	Railing Cap	/	A/M L N/A	Y				
	Handrail	/	A/M L N/A	Y				
	Balusters	/	A/M L N/A	Y				
	Lower rail	/	A/M L N/A	Y				
	Treads	0.0	A/M L N/A	Y				
	Risers	0.2	A/M L N/A	Y				
	Stringer	0.1	A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Floor Casing	0.1	A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				
			M/I A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 288 SQ. IN.)	IC DATE	IC METHOD

Gary Marcello | M3169 | Gary Marcello | 11/14/06 | Page 12 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date

Address of Property 27 TYLER OXFORD ST | Apt # 1-2 | City Haverhill

EXTERIOR

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Siding	9.9	L N/A	Y				INT
	Corner Boards	9.9	L N/A	Y				INT
	Lower Trim	/	L N/A	Y				
	Upper Trim	N/A	L N/A	Y				INT
	Win Above 5'	N/A	L N/A	Y				INT
	Porch Above 5'	/	L N/A	Y				
D *	Storm Door	/	A/M L N/A	Y				
	Door	1.1	A/M L N/A	Y				SCR
	Door Casing	9.9	A/M L N/A	Y				SCR
	Door Jamb	9.9	A/M L N/A	Y				SCR
	Threshold	9.9	A/M L N/A	Y				SCR
	Kickplate	/	A/M L N/A	Y				
D	Storm Door	\	A/M L N/A	Y				
	Door	\	A/M L N/A	Y				
	Door Casing	\	A/M L N/A	Y				
	Door Jamb	\	A/M L N/A	Y				
	Threshold	\	A/M L N/A	Y				
	Kickplate	\	A/M L N/A	Y				
D	Door	\	A/M L N/A	Y				
	Door Casing	\	A/M L N/A	Y				
	Door Jamb	\	A/M L N/A	Y				
	Threshold	\	A/M L N/A	Y				
D	Door	\	A/M L N/A	Y				
	Door Casing	\	A/M L N/A	Y				
	Door Jamb	\	A/M L N/A	Y				
	Threshold	\	A/M L N/A	Y				
D	Window Sill	\	A/M L N/A	Y				
	Win Casing	\	A/M L N/A	Y				
	Window Sash	\	A/M L N/A	Y				
D	Window Sill	\	A/M L N/A	Y				
	Win Casing	\	A/M L N/A	Y				
	Window Sash	\	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

* ANY PART OF DOOR 1/2" OR GREATER MUST BE SCRAPED

SIDE D	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
D	Window Sill	\	A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
D	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
D 1	Cellar Win Sill	6.6	A/M L N/A	Y				SCR
	Cel Win Sash	9.9	A/M L N/A	Y				SCR
	Cel Win Frame	9.9	A/M L N/A	Y				SCR
D 2	Cellar Win Sill	6.3	A/M L N/A	Y				SCR
	Cel Win Sash	Encl	A/M L N/A	Y				SCR
	Cel Win Frame	Encl	A/M L N/A	Y	PL 2x1 PLEXI		FRAME	SCR
D 3	Cellar Win Sill	9.9	A/M L N/A	Y				SCR
	Cel Win Sash	9.9	A/M L N/A	Y				SCR
	Cel Win Frame	9.9	A/M L N/A	Y				SCR
D	Cellar Win Sill	/	A/M L N/A	Y				
	Cel Win Sash	/	A/M L N/A	Y				
	Cel Win Frame	/	A/M L N/A	Y				
D	Foundation	NC	L N/A	Y				
	Bulkhead	/	A/M L N/A	Y				
	Fences	/	A/M L N/A	Y				
	Shutters	N/A	A/M L N/A	Y				
D	Newel post	\	A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower Rail		A/M L N/A	Y				
	Treads		A/M L N/A	Y				
	Risers		A/M L N/A	Y				
	Stringer		A/M L N/A	Y				
DRAINSPOUT		N/A	A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
D			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE D	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
D				
D				
D				
D				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				
Comments:				

GARY MARCELLO | 2360 | Gary Marcello | 11/14/06
Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic # | Signature | Date

Address of Property 37 MAXFORT | Apt # | City HAVERHILL

EXTERIOR

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Siding	LC	L N/A	Y				SCR
	Corner Boards	9G	L N/A	Y				SCR
	Lower Trim		L N/A	Y				
	Upper Trim	NA	L N/A	Y				SCR
	Win Above 5'	NA	L N/A	Y				SCR
	Porch Above 5'		L N/A	Y				
C	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
C	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
C	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
C	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
C	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
C	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
C	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
C	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
C	Cellar Win Sill	9G	A/M L N/A	Y				SCR
	Cel Win Sash	9G	A/M L N/A	Y				VR
	Cel Win Frame	9G	A/M L N/A	Y				COV
C	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
C	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
C	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
C	Foundation	LC	L N/A	Y				
	Bulkhead		A/M L N/A	Y				
	Fences		A/M L N/A	Y				
	Shutters		A/M L N/A	Y				
C	Newel post		A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower Rail		A/M L N/A	Y				
	Treads		A/M L N/A	Y				
	Risers		A/M L N/A	Y				
	Stringer		A/M L N/A	Y				
C			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
C				
C				
C				
C				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				
Comments:				

Gary Marcella | M3169 | Gary Marcella | 11/14/06 | Page 24 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date

Address of Property 27 #29 X FORD ST. | Apt # 1-2 | City HAVERHILL

EXTERIOR

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Siding	1.2	A/M L N/A	Y				MS
	Corner Boards	99	A/M L N/A	Y				MS
	Lower Trim	/	A/M L N/A	Y				
	Upper Trim	N/A	A/M L N/A	Y				MS
	Win Above 5'	N/A	A/M L N/A	Y				HA
	Porch Above 5'	/	A/M L N/A	Y				
B	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
B	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
B	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
B	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
B	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
B	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
B	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
B	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
B1	Cellar Win Sill	99	A/M L N/A	Y				SCR
	Cel Win Sash	99	A/M L N/A	Y				VR
	Cel Win Frame	99	A/M L N/A	Y				CW
B2	Cellar Win Sill	99	A/M L N/A	Y				SCR
	Cel Win Sash	99	A/M L N/A	Y				VR
	Cel Win Frame	99	A/M L N/A	Y				CW
B3	Cellar Win Sill	99	A/M L N/A	Y				SCR
	Cel Win Sash	CW	A/M L N/A	Y				VR
	Cel Win Frame	CW	A/M L N/A	Y				CW
B	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
B	Foundation	NL	L N/A	Y				
	Bulkhead		A/M L N/A	Y				
	Fences		A/M L N/A	Y				
	Shutters	NL	A/M L N/A	Y	>5'			
B	Newel post		A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower Rail		A/M L N/A	Y				
	Treads		A/M L N/A	Y				
	Risers		A/M L N/A	Y				
	Stringer		A/M L N/A	Y				
B			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
B				
B				
B				
B				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				
Comments:				

Greg Marcello | M3169 | Mary Morse | 11/14/06 | Page 25 Of ___

Inspector (print) | Lic # | Signature | Date

Risk Assessor (print) | Lic# | Signature | Date

Address of Property 27 Oxford ST. | Apt # 1-2 | City Haverhill

EXTERIOR

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Siding	99	L N/A	Y				
	Corner Boards	99	D N/A	Y				MI
	Lower Trim	/	L N/A	Y				
	Upper Trim	NR	L N/A	Y				INT
	Win Above 5'	NR	L N/A	Y				INT
	Porch Above 5'	NR	L N/A	Y				INT
A	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
A	Storm Door		A/M L N/A	Y				
	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
	Kickplate		A/M L N/A	Y				
A	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
A	Door		A/M L N/A	Y				
	Door Casing		A/M L N/A	Y				
	Door Jamb		A/M L N/A	Y				
	Threshold		A/M L N/A	Y				
A	Window Sill	99	A/M D N/A	Y				
	Win Casing	99	A/M D N/A	Y				
/	Window Sash	NR	A/M L N/A	Y				
A	Window Sill	3.0	A/M D N/A	Y				
	Win Casing	99	A/M D N/A	Y				
2	Window Sash	NR	A/M L N/A	Y				

COMMENTS / STRUCTURAL DEFECTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD	URG HAZ?	IC DATE	IC METH	DELEAD DATE	DELEAD METH
A	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
A	Window Sill		A/M L N/A	Y				
	Win Casing		A/M L N/A	Y				
	Window Sash		A/M L N/A	Y				
A	Cellar Win Sill	99	A/M D N/A	Y				SCR
	Cel Win Sash	cov	A/M L N/A	Y				
	Cel Win Frame	cov	A/M L N/A	Y	Pbox			
A	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
A	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
A	Cellar Win Sill		A/M L N/A	Y				
	Cel Win Sash		A/M L N/A	Y				
	Cel Win Frame		A/M L N/A	Y				
A	Foundation	NC	L N/A	Y				
	Bulkhead	/	A/M L N/A	Y				
	Fences	/	A/M L N/A	Y				
	Shutters	/	A/M L N/A	Y				
A	Newel post		A/M L N/A	Y				
	Railing Cap		A/M L N/A	Y				
	Handrail		A/M L N/A	Y				
	Balusters		A/M L N/A	Y				
	Lower Rail		A/M L N/A	Y				
	Treads		A/M L N/A	Y				
	Risers		A/M L N/A	Y				
	Stringer		A/M L N/A	Y				
A			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				
			A/M L N/A	Y				

Excluded Surfaces: Surfaces listed in this box can be made intact only by a licensed deleader

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	IC DATE	IC METH
A				
A				
A				
A				

Soil Test Results

(Must be less than 400 ppm for play area / 1200 ppm for bare soil)

LOCATION	AREA MEASUREMENT (Square Feet)	RESULT (PPM)	REMED DATE	REMED METH
Play Area				
Bare soil				
Comments:				

GARY MARCIELLO M3164 Gary Marciello 11/14/06 Page 24 of ___

Inspector (print) Lic # Signature Date

Address of Lead Inspection 2704 FORD ST. Apt # 1 Com City HAVERHILL

PORCH A EL1

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Siding	9.9		L			
	Corner Boards	/		L			
	Upper Trim	NA		L			
	Ceiling	NA		L			
	Joists	/		L			
	Door	0.5	A/M	L			
	Storm Door	NI	A/M	L			
C	Door Casing	9.9	A/M	L			SCR
	Door Jamb	9.9	A/M	L			SCR
1	Threshold	0.2	A/M	L			
	Kickplate	/	A/M	L			
	Door	0.6	A/M	L			
	Storm Door	0.0	A/M	L			
C	Door Casing	9.9	A/M	L			SCR
	Door Jamb	9.9	A/M	L			SCR
2	Threshold	1.2	A/M	L			SCR
	Kickplate	/	A/M	L			
	Window Sill	9.9	A/M	L			SCR
C	Win Casing	9.9	A/M	L			SCR
	Window Sash	NR	A/M	L			
	Mullions	/	A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			

COMMENTS:

* BASIS 7-7 A/M

MOLD 7-7 A/M

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
*	Support Clmns	6.1	A/M	L	>6 BASIS		SCR
	Newel post	/	A/M	L	BRICK	NI	
	Railing Cap	9.9	A/M	L			RCP
	Handrail	/	A/M	L			
	Balusters	9.9	A/M	L			RCP
	Lower Rail	9.9	A/M	L			RCP
	Treads	NC	A/M	L			
	Risers	NC	A/M	L			
	Stringer	/	A/M	L			
	Low Walls	/	A/M	L			
	Lattice	/	A/M	L			
	Low Trim	/		L			
	Floor	FOAM		L			
	Threshold	/	A/M	L			

COMMENTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

GARY MARCELLO M3169 Gary Marcello 11/14/06 Page 27 of 27

Inspector (print) Lic # Signature Date

Address of Lead Inspection 270 EXETER ST Apt # COMM City HAVERHILL

PORCH C SC

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
A	Siding	16		L			
	Corner Boards			L			
	Upper Trim	NA		L			
	Ceiling	NL		L			
	Joists	—		L			
A	Door	06	A/M	L			
	Storm Door	00	A/M	L			
	Door Casing	99	A/M	L			SCR
	Door Jamb	99	A/M	L			SCR
	Threshold	2.4	A/M	L			SCR
	Kickplate		A/M	L			
	Door		A/M	L			
	Storm Door		A/M	L			
	Door Casing		A/M	L			
	Door Jamb		A/M	L			
	Threshold		A/M	L			
	Kickplate		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			
	Window Sill		A/M	L			
	Win Casing		A/M	L			
	Window Sash		A/M	L			
	Mullions		A/M	L			

COMMENTS:

SIDE	LOCATION/ SURFACE	LEAD	TYPE OF HAZARD		COMMENTS	DELEAD DATE	DELEAD METHOD
	Support Cmns	[illegible]	A/M	L			SCR
	Newel post	01	A/M	L			
	Railing Cap	01	A/M	L			
	Handrail	01	A/M	L			
	Balusters		A/M	L			
	Lower Rail	00	A/M	L			
	Treads	NL	A/M	L			
	Risers	NL	A/M	L			
	Stringer	NO	A/M	L			
	Low Walls		A/M	L			
	Lattice	02	A/M	L			
	Low Trim	01		L			
	Floor	NL		L			
	Threshold	—	A/M	L			

COMMENTS:

EXCLUDED SURFACES: Surfaces listed in these boxes can be made intact only by a licensed deleader.

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD

SIDE	LOCATION	MEASURE: LOOSE PAINT (MORE THAN 1440 SQ. IN.)	DELEAD DATE	DELEAD METHOD